

CLASSIFIED MESSAGE

DATE 1818Z 14 JUL 65

T O P S E C R E T

ROUTING		
1	Deck	9
2		10
3		11
4	Intell	12
5	Eden	13
6	KB	14
7		15
8		16

PRIORITY

TOR: 1830Z 14 JUL 65

OSA 1-20  
Gt

IN 97600

TO PRIORITY

INFO

CITE

4954

IDEALIST

ATTN: [REDACTED]

SUBJECT: EVALUATION OF MISSION (C365C)

1. CAMERA C119 WAS USED IN MISSION C365C FLOWN ON 3 JULY 65.  
PROCESSING WAS ACCOMPLISHED IN THE FIELD.

## 2. ORIGINAL NEGATIVE:

A. EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: HEAT SPLICES ARE PRESENT BETWEEN FRAMES 93/94,  
226/227, 619/620, 624/625, 718/719, 851/852, 873/874, 984/985  
AND 1117/1118. WAVERING PLUS DENSITY STREAKS, NEAR THE INBOARD  
EDGE, ARE PRESENT INTERMITTENTLY ON FRAMES 626 TO 652, 671 TO 715  
AND 1075 TO 1107. EMULSION LIFTS ARE NOTED IN FRAME 624. TWO  
SMALL STAINS OF AN UNKNOWN SUBSTANCE OCCUR IN FRAME 208.

C. 9L SIDE: THERE IS AN AREA OF SLIGHT FOG EXTENDING FROM  
THE INBOARD EDGE OF THE FILM IN FRAME 17. HEAT SPLICES OCCUR  
BETWEEN FRAMES 93/94, 226/227, 229/230, 359/360, 492/493, 499/500,  
615/616, 624/625, 718/719, 851/852, 871/872, 984/985 AND

T O P S E C R E T

GROUP 8  
EXCLUDED FROM AUTOMATIC  
DOWNGRADING AND DECLASSIFICATION

25X1A

T O P S E C R E T

IN 97600

4954

PAGE TWO

1117/1118. A BAND OF FOG ROUGHLY 1.9" WIDE APPEARS ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. FAINT IMAGES OF THE ADJACENT POSITION INDICATOR IS IMAGED. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 347.

D. BOTH SIDES: INTERMITTENT EDGE STATIC IS PRESENT ALONG BOTH FILM'S EDGES. PRESSURE ROLLER STATIC (CHATTER) OCCURS NEAR THE INBOARD EDGE THROUGHOUT THE FILM. FRAMES ARE TITLED CONSECUTIVELY FROM 0000 THROUGH 1189.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THE MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 30 PERCENT OF THE MISSION.

END OF MESSAGE

T O P S E C R E T